

## **Regulations of Laser Workshops**

- 1. Only students from the School of architecture who have attended the Laser Workshop current year safety-training seminar are permitted to use the machines and tools.
- 2. Students are solely responsible for their personal safety and security when using the equipment and facilities in the Laser Workshops at all times.
- 3. Doors of the Laser Workshops should be kept closed at all times.
- 4. Only cardboard and acrylic are allowed to be cut by the laser cutting machines.
- 5. Never leave the laser system running unattended for any reason. Turn off the power supply immediately when you are not using the machines.
- 6. No smoking, food and drinks are allowed in the Laser Workshops.
- 7. No spray activities are allowed in the Laser Workshops.
- 8. You are not allowed to store your model and materials in the room. Any remaining materials left unattended in the Laser Workshops will be disposed of without prior notification.
- 9. Keep the working area and facilities clean and tidy after use.
- 10. Please dispose all recyclable waste to the recycle bins inside the Laser Workshops. Large and heavy recyclable materials should be placed to the recyclable waste collection point at LG/F.
- 11. If equipment is fitted with protection device, they must be used. Equipment should never be used if the protection device have been removed or are found malfunctioning.
- 12. Do not carry loads to such a weight that may be dangerous or with the vision obstructed.
- 13. All accidents/incidents/occupational ill health must be reported thereby the staff.
- 14. In the event of fire, leave the building immediately. Break glass of the nearby fire alarm call point to alert other users in the building and proceed to the assembly point.
- 15. Contact the staff of Workshop at 3943-6585 or send email to <a href="mailto:lg.workshop@eservices.cuhk.edu.hk">lg.workshop@eservices.cuhk.edu.hk</a> if you have any enquiries.
- 16. In case of emergencies or any irregularities found, push down 'EMERGENCY STOP' button and switch off the electric power of the laser cutting machines.
- 17. Please contact the following person in case of emergencies / irregularities found:

Technician in-charge Leo DAI 3943-6585

 Safety coordinator
 Max LEE
 3943-6589/3943-6585

 General Office
 3943-6583/3943-1027

 Security Office (Non-office hours)
 3943-7999 (24-hr)

Ambulance 2735-3355